

START


0016283

DOE/RL-91-47

Quarterly Report of RCRA Groundwater Monitoring Data for Period April 1, 1991 through June 30, 1991



United States
Department of Energy
Richland, Washington



Approved for Public Release

**THIS PAGE INTENTIONALLY
LEFT BLANK**

2001 932
07/11/01
0001

LEGAL DISCLAIMER

This report was prepared as an account of work sponsored by an agency of the United States Government. Neither the United States Government nor any agency thereof, nor any of their employees, nor any of their contractors, subcontractors or their employees, makes any warranty, express or implied, or assumes any legal liability or responsibility for the accuracy, completeness, or any third party's use or the results of such use of any information, apparatus, product, or process disclosed, or represents that its use would not infringe privately owned rights. Reference herein to any specific commercial product, process, or service by trade name, trademark, manufacturer, or otherwise, does not necessarily constitute or imply its endorsement, recommendation, or favoring by the United States Government or any agency thereof or its contractors or subcontractors. The views and opinions of authors expressed herein do not necessarily state or reflect those of the United States Government or any agency thereof.

This report has been reproduced from the best available copy.

Printed in the United States of America

DISCLM-2.CHP (1-91)

**THIS PAGE INTENTIONALLY
LEFT BLANK**

Quarterly Report of RCRA Groundwater Monitoring Data for Period April 1, 1991 through June 30, 1991

Geosciences Group
Westinghouse Hanford Company
Environmental Division

Date Published
September 1991



United States
Department of Energy

P.O. Box 550
Richland, Washington 99352

**THIS PAGE INTENTIONALLY
LEFT BLANK**

LIST OF FIGURES

1-1	Locations of the RCRA Groundwater Monitoring Projects and Landmarks on the Hanford Site	3
-----	---	---

LIST OF TABLES

2-1	RCRA Water Level Measurement Report 300 Area Process Trenches - Second Quarter 1991	6
3-1	RCRA Water Level Measurement Report 183-H Solar Evaporation Basins - Second Quarter 1991	12
4-1	RCRA Water Level Measurement Report Low-Level Burial Grounds - Second Quarter 1991	18
5-1	RCRA Water Level Measurement Report 100-N Area - Second Quarter 1991	24
6-1	RCRA Water Level Measurement Report 216-A-29 Ditch - Second Quarter 1991	30
7-1	RCRA Water Level Measurement Report 216-A-10 Crib - Second Quarter 1991	34
8-1	RCRA Water Level Measurement Report 216-A-36B Crib - Second Quarter 1991	36
9-1	RCRA Water Level Measurement Report 216-B-3 Pond System - Second Quarter 1991	38
10-1	RCRA Water Level Measurement Report 2101-M Pond - Second Quarter 1991	42
11-1	RCRA Water Level Measurement Report Grout Treatment Facility - Second Quarter 1991	44
12-1	RCRA Water Level Measurement Report Single-Shell Tanks - Second Quarter 1991	48
13-1	RCRA Water Level Measurement Report NRDWL - Second Quarter 1991 . .	52

CONTENTS

1.0	INTRODUCTION	1
2.0	300 AREA PROCESS TRENCHES	5
3.0	183-H SOLAR EVAPORATION BASINS	11
4.0	200 AREAS LOW-LEVEL BURIAL GROUNDS	17
5.0	100-N AREA RCRA SITES	23
6.0	216-A-29 DITCH	29
7.0	216-A-10 Crib	33
8.0	216-A-36B Crib	35
9.0	216-B-3 POND SYSTEM	37
10.0	2101-M POND	41
11.0	GROUT TREATMENT FACILITY	43
12.0	SINGLE-SHELL TANKS	47
13.0	NONRADIOACTIVE DANGEROUS WASTE LANDFILL	51
14.0	REFERENCES	55

2

ACRONYMS

CERCLA	<i>Comprehensive Environmental Response, Compensation and Liability Act of 1980</i>
CLP	Contract Laboratory Program
HEHF	Hanford Environmental Health Foundation
LLWMA	Low-Level Waste Management Area
NRDWL	Nonradioactive Dangerous Waste Landfill
PNL	Pacific Northwest Laboratory
QA	quality assurance
QC	quality control
RCRA	<i>Resource Conservation and Recovery Act of 1976</i>
SST	Single-Shell Tanks
UST	United States Testing Company, Inc.
WMA	Waste Management Area

Three RCRA facilities had groundwater samples collected during the month of June. A complete set of data has not been received for these facilities; the data will be reported in the next quarterly report (for period July 1991 through September 1991).

Water level data have continued to be collected at each of the facilities. This report contains the water level measurements from 14 Hanford Site RCRA groundwater projects. The location of each facility is shown in Figure 1-1. Water level measurements have been collected for the Liquid Effluent Retention Facility, 216-S-10 Facility, 216-U-12 Crib, 216-B-63 Trench, and 100-D Area. These facilities have not initiated the background monitoring program; therefore, the measurements are not provided in this report.

The water levels were collected in accordance with the Hanford Site approved procedure found in WHC-CM-7-7 (WHC 1991). Water level measurements were obtained using standardized, weighted, steel measuring tapes. Readings were repeated until a consistent measurement was obtained. Readings are considered consistent if they are within ± 0.02 ft.

The measuring device was decontaminated before each series of measurements and after each well measurement to ensure the safety of personnel and to prevent cross-contamination of wells.

The number of significant digits listed in the water level tables is not indicative of the accuracy.

Most facilities have not had any changes to their monitoring networks. Well location maps for these facilities can be found in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Any changes made to monitoring networks for this period are identified in the following sections.

1.0 INTRODUCTION

Hanford Site interim-status groundwater monitoring projects are conducted as either background, indicator parameter evaluation, or groundwater quality assessment monitoring programs as defined in the *Resource Conservation and Recovery Act of 1976* (RCRA); and 40 CFR 265, *Interim Status Standards for Owners and Operators of Hazardous Waste Treatment, Storage, and Disposal Facilities*, as amended (EPA 1989). Compliance with the 40 CFR 265 regulations are required by the Washington Administrative Code 173-303 (Ecology 1991). This submittal provides data obtained from groundwater monitoring activities for April 1, 1991 through June 30, 1991.


On June 1, 1990, Pacific Northwest Laboratory (PNL) announced the termination of its subcontract with United States Testing Company, Inc. (UST), which was responsible for analyzing chemistry samples and providing the resulting data. The U.S. Department of Energy Field Office, Richland, currently is in the process of awarding a contract to a suitable analytical laboratory.

In February 1991, a list of wells was assembled for priority sampling. The list includes 52 groundwater monitoring wells from RCRA and operational groundwater monitoring programs across the Hanford Site. This list, along with the constituents analyzed for, were presented in the previous quarterly report (DOE-RL 1991b).

The samples were collected in March and April 1991 and submitted to laboratories contracted to perform *Comprehensive Environmental Response, Compensation, and Liability Act of 1980* (CERCLA) analyses. Laboratory analyses performed under the Contract Laboratory Program (CLP), the program specified for CERCLA, vary from the requirements for RCRA analyses. Although the CLP data validation requirements exceed those of RCRA, the CLP contract does not include all of the RCRA constituents.

These water sampling data were collected to assess any hydrochemical changes that may have occurred, because sampling ceased last year. The data are being used for information purposes only to aid in groundwater flow and contaminant transport interpretation. The data are not included in this quarterly report because they were not produced in accordance with RCRA protocol. This information is available on request.

Groundwater sampling was resumed on the Hanford Site on June 6, 1991. The laboratory that is performing the majority of the analyses, under an interim contract, is IT Analytical Services. Nitrates analysis is being performed by PNL, and the Hanford Environmental and Health Foundation (HEHF) will be performing coliform analysis in the future. Currently, no laboratory is available to perform the inductively coupled plasma method for metals detection. These samples are being archived for future analysis. Westinghouse Hanford Company is in the process of initiating an internal quality assurance/quality control (QA/QC) laboratory to evaluate the PNL primary contract laboratory performance.



DOE/RL-91-47

GEOSC\110890-B

Figure 1-1. Locations of the RCRA Groundwater Monitoring Projects and Landmarks on the Hanford Site.

Table 2-1. RCRA Water Level Measurement Report 300 Area
Process Trenches - Second Quarter 1991. (sheet 1 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
Wells Monitoring the Top of the Unconfined Aquifer			
399-1-1	4/25/91	29.44	346.46
	5/29/91	28.82	347.08
	6/18/91	28.25	347.65
399-1-10	4/01/91	28.65	345.00
	4/25/91	27.04	346.61
	5/29/91	26.09	347.56
	6/18/91	26.86	346.79
399-1-11	4/25/91	31.30	346.49
	5/29/91	30.38	347.41
	6/18/91	31.00	346.79
399-1-12	4/25/91	38.39	346.06
	5/29/91	37.47	346.98
	6/18/91	37.90	346.55
399-1-13	4/01/91	43.76	344.86
	4/25/91	42.58	346.04
	5/29/91	41.66	346.96
	6/18/91	41.98	346.64
399-1-14	4/25/91	36.93	346.30
	5/29/91	36.04	347.19
	6/18/91	36.25	346.98
399-1-15	4/25/91	33.08	346.51
	5/29/91	32.27	347.32
	6/18/91	32.49	347.10
399-1-16A	4/01/91	37.13	344.38
	4/25/91	35.54	345.97
	5/29/91	34.68	346.83
	6/18/91	35.32	346.19
399-1-17A	4/01/91	32.94	344.53
	4/25/91	31.56	345.91
	5/29/91	30.67	346.80
	6/18/91	31.15	346.32
	6/24/91	33.39	344.18*
399-1-18A	4/01/91	45.11	345.72
	4/25/91	44.10	346.73
	5/29/91	43.33	347.50
	6/18/91	43.29	347.54

2.0 300 AREA PROCESS TRENCHES

**J. V. Borghese
Pacific Northwest Laboratory**

The groundwater monitoring network for this RCRA facility has not changed from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Please refer to that report for a description of the facility and the monitoring network.

Water level data for wells in the vicinity of the trenches for the second quarter of 1991 are presented in Table 2-1.

Table 2-1. RCRA Water Level Measurement Report 300 Area
Process Trenches - Second Quarter 1991. (sheet 3 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
399-3-6	4/25/91	47.07	345.78
	5/29/91	46.25	346.60
	6/18/91	46.63	346.22
399-3-7	4/25/91	48.41	345.81
	5/29/91	47.57	346.65
	6/18/91	48.08	346.14
399-3-9	4/25/91	41.45	345.86
	5/29/91	40.59	346.72
	6/18/91	41.39	345.92
399-4-1	4/25/91	49.30	345.70
	5/29/91	48.46	346.54
	6/18/91	49.29	345.71
399-4-10	4/25/91	31.80	345.79
	5/29/91	30.94	346.65
	6/18/91	31.86	345.73
399-4-11	4/25/91	58.80	345.73
	5/29/91	57.96	346.57
	6/18/91	58.58	345.95
399-4-7	4/25/91	31.24	345.75
	5/29/91	30.40	346.59
	6/18/91	31.36	345.63
399-4-9	4/25/91	35.57	345.83
	5/29/91	34.70	346.70
	6/18/91	35.58	345.82
399-5-1	4/25/91	49.94	345.66
	5/29/91	49.15	346.45
	6/18/91	49.44	346.16
399-6-1	4/25/91	41.18	345.75
	5/29/91	40.44	346.49
	6/18/91	40.37	346.56
399-8-1	4/25/91	48.95	345.93
	5/29/91	48.20	346.68
	6/18/91	48.24	346.64
399-8-2	4/25/91	50.18	345.88
	5/29/91	49.47	346.59
	6/18/91	49.01	347.05

Table 2-1. RCRA Water Level Measurement Report 300 Area
Process Trenches - Second Quarter 1991. (sheet 2 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
399-1-19	4/25/91	28.62	346.02
	5/29/91	27.70	346.94
	6/18/91	28.36	346.28
399-1-3	4/25/91	38.76	345.97
	5/29/91	37.86	346.87
	6/18/91	38.50	346.23
399-1-4	4/25/91	34.21	346.90
	5/29/91	33.28	347.83
	6/18/91	33.64	347.47
399-1-5	4/25/91	33.68	346.14
	5/29/91	32.75	347.07
	6/18/91	33.44	346.38
399-1-7	4/25/91	39.69	345.94
	5/29/91	38.82	346.81
	6/18/91	39.44	346.19
399-1-8	4/25/91	38.99	345.92
	5/29/91	38.10	346.81
	6/18/91	38.69	346.22
399-2-1	4/25/91	29.28	345.98
	5/29/91	28.36	346.90
	6/18/91	29.13	346.13
399-2-2	4/25/91	29.55	345.98
	5/29/91	28.69	346.84
	6/18/91	29.34	346.19
399-2-3	4/25/91	29.49	345.95
	5/29/91	28.62	346.82
	6/18/91	29.30	346.14
399-3-1	4/25/91	38.55	345.88
	5/29/91	37.65	346.78
	6/18/91	38.46	345.97
399-3-10	4/25/91	39.60	345.80
	5/29/91	38.73	346.67
	6/18/91	39.59	345.81
399-3-12	4/25/91	40.59	345.79
	5/29/91	39.73	346.65
	6/18/91	40.38	346.00

This page intentionally left blank.

91121193740

Table 2-1. RCRA Water Level Measurement Report 300 Area
Process Trenches - Second Quarter 1991. (sheet 4 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
399-8-3	4/25/91	47.01	346.10
	5/29/91	46.25	346.86
	6/18/91	46.17	346.94
699-S27-E14	4/25/91	54.10	345.66
	5/27/91	53.28	346.48
	6/18/91	54.11	345.65
Wells Monitoring the Bottom of the Unconfined Aquifer			
399-1-16B	4/25/91	34.93	346.21
	5/29/91	34.10	347.04
	6/18/91	34.74	346.40
399-1-17B	4/25/91	31.80	346.07
	5/29/91	30.86	347.01
	6/18/91	31.39	346.48
399-1-18B	4/25/91	42.97	346.97
	5/29/91	42.20	347.74
	6/18/91	42.29	347.65
Wells Monitoring the Confined Aquifer			
399-1-17C	4/25/91	2.00	376.13
	5/29/91	2.08	376.05
	6/18/91	2.32	375.81
399-1-18C	4/25/91	40.68	347.37
	5/29/91	39.93	348.12
	6/18/91	39.92	348.13
399-1-9	4/25/91	19.24	365.50
	5/29/91	19.02	365.78
	6/18/91	19.41	365.39

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

Table 3-1. RCRA Water Level Measurement Report 183-H Solar Evaporation Basins - Second Quarter 1991. (sheet 1 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
Wells Monitoring the Top of the Unconfined Aquifer (Hanford Formation)			
199-H3-1	4/11/91	43.77	377.71
	4/30/91	43.55	377.93
	5/16/91	43.45	378.03
	5/29/91	43.29	378.19
	6/06/91	44.08	377.40*
	6/20/91	42.71	378.77
199-H3-2A	4/11/91	40.09	377.74*
	4/11/91	40.07	377.76
	4/30/91	39.78	378.05
	5/16/91	39.83	378.00
	5/29/91	39.42	378.41
	6/06/91	39.06	378.77*
199-H3-2B	6/20/91	38.75	379.08
	4/11/91	40.66	377.76
	4/30/91	40.34	378.08
	5/16/91	40.41	378.01
	5/29/91	39.99	378.43
	6/20/91	39.33	379.09
199-H4-10	4/11/91	26.14	378.30
	4/30/91	26.58	377.86
	5/16/91	27.21	377.23
	5/29/91	24.52	379.92
	6/20/91	27.29	377.15
199-H4-11	4/11/91	38.88	377.96
	4/30/91	39.33	377.51
	5/16/91	39.03	377.81
	5/29/91	37.08	379.76
	6/07/91	36.72	380.12*
	6/20/91	40.04	376.80
199-H4-12A	4/11/91	35.59	377.91*
	4/11/91	35.32	378.18
	4/30/91	35.82	377.68
	5/16/91	35.23	378.27
	5/29/91	33.38	380.12
	6/07/91	33.23	380.27*
	6/20/91	36.73	376.77

3.0 183-H SOLAR EVAPORATION BASINS

R. E. Peterson
Westinghouse Hanford Company

The groundwater monitoring network for this RCRA facility has not changed from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Please refer to that report for a description of the facility and the monitoring network. Groundwater samples were collected in June. Results of the analyses will be reported next quarter.

Water level data for wells in the vicinity of the basins for the second quarter of 1991 are presented in Table 3-1.

Table 3-1. RCRA Water Level Measurement Report 183-H Solar Evaporation Basins - Second Quarter 1991. (sheet 3 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
199-H4-18	4/10/91	44.72	377.10*
	4/11/91	44.49	377.33
	4/30/91	44.11	377.71
	5/16/91	44.66	377.16
	5/29/91	43.01	378.81
	6/20/91	43.42	378.40
199-H4-3	4/10/91	43.21	377.08*
	4/11/91	43.00	377.29
	4/30/91	42.58	377.71
	5/16/91	43.33	376.96
	5/29/91	41.27	379.02
	6/07/91	41.06	379.23*
	6/20/91	41.91	378.38
199-H4-4	4/11/91	35.72	377.98*
	4/11/91	35.59	378.11
	4/30/91	36.10	377.60
	5/16/91	35.56	378.14
	5/29/91	33.73	379.97
	6/06/91	34.34	379.36*
	6/20/91	37.03	376.67
199-H4-5	4/11/91	38.72	377.49
	4/30/91	38.56	377.65
	5/16/91	39.17	377.04
	5/29/91	36.42	379.79
	6/20/91	38.46	377.75
199-H4-6	4/11/91	41.83	377.75
	4/30/91	41.48	378.10
	5/16/91	41.58	378.00
	5/29/91	41.13	378.45
	6/10/91	40.64	378.94*
	6/20/91	40.48	379.10
199-H4-7	4/11/91	43.16	377.43
	4/30/91	42.71	377.88
	5/16/91	43.10	377.49
	5/29/91	41.95	378.64
	6/06/91	41.71	378.88*
	6/20/91	41.77	378.82
199-H4-8	4/11/91	42.63	377.37
	4/30/91	42.14	377.86
	5/16/91	42.70	377.30
	5/29/91	41.02	378.98
	6/20/91	41.23	378.77

Table 3-1. RCRA Water Level Measurement Report 183-H Solar Evaporation Basins - Second Quarter 1991. (sheet 2 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
199-H4-12B	4/11/91	35.41	378.11
	4/30/91	35.83	377.69
	5/16/91	35.35	378.17
	5/29/91	33.46	380.06
	6/20/91	36.61	376.91
199-H4-13	4/11/91	40.26	377.94
	4/20/91	40.93	377.27
	5/16/91	40.47	377.73
	5/29/91	38.69	379.51
	6/20/91	41.73	376.47
199-H4-14	4/11/91	43.02	377.57
	4/30/91	42.68	377.91
	5/16/91	42.80	377.79
	5/29/91	42.27	378.32
	6/07/91	41.87	378.72*
	6/20/91	41.64	378.95
199-H4-15A	4/11/91	29.03	378.18
	4/30/91	29.28	377.93
	5/16/91	29.02	378.19
	5/29/91	27.02	380.19
	6/20/91	30.02	377.19
199-H4-15B	4/11/91	28.73	378.19
	4/30/91	29.02	377.90
	5/16/91	28.80	378.12
	5/29/91	26.86	380.06
	6/20/91	29.74	377.18
199-H4-16	4/11/91	47.11	377.12
	4/30/91	46.76	377.47
	5/16/91	46.89	377.34
	5/29/91	46.30	377.93
	6/07/91	45.94	378.29*
	6/20/91	45.73	378.50
199-H4-17	4/11/91	41.56	377.53
	4/30/91	41.08	378.01
	5/16/91	41.79	377.30
	5/29/91	39.65	379.44
	6/20/91	40.47	378.62

Table 3-1. RCRA Water Level Measurement Report 183-H Solar Evaporation Basins - Second Quarter 1991. (sheet 5 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
Well Monitoring the Bottom of the Unconfined Aquifer (Ringold Formation)			
199-H4-15CQ	4/11/91	12.15	395.12
	4/30/91	12.13	395.14
	5/16/91	12.48	394.79
	5/29/91	11.55	395.72
	6/20/91	12.78	394.49

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

Table 3-1. RCRA Water Level Measurement Report 183-H Solar Evaporation Basins - Second Quarter 1991. (sheet 4 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
199-H4-9	4/11/91	40.72	377.36
	4/30/91	40.28	377.80
	5/16/91	40.96	377.12
	5/29/91	37.83	380.25
	6/06/91	38.94	379.14*
	6/20/91	39.55	378.53

Wells Monitoring Upper Levels in the Unconfined Aquifer
(Ringold Formation)

199-H3-2C	4/11/91	40.45	377.77
	4/30/91	40.12	378.10
	5/16/91	40.26	377.96
	5/29/91	39.63	378.59
	6/06/91	39.39	378.83*
	6/20/91	39.30	378.92
199-H4-12C	4/11/91	35.30	378.22
	4/30/91	36.00	377.52
	5/16/91	35.87	377.65
	5/29/91	34.16	379.36
	6/07/91	33.51	380.01*
	6/20/91	36.66	376.86
199-H4-15CS	4/11/91	29.08	378.36
	4/30/91	29.75	377.69
	5/16/91	29.59	377.85
	5/29/91	27.82	379.62
	6/20/91	30.54	376.90

Well Monitoring Mid-Level in the Unconfined Aquifer
(Ringold Formation)

199-H4-15CR	4/11/91	31.58	375.79
	4/30/91	31.43	375.94
	5/16/91	31.28	376.09
	5/29/91	30.84	376.53
	6/20/91	30.33	377.04

Table 4-1. RCRA Water Level Measurement Report Low-Level Burial Grounds - Second Quarter 1991. (sheet 1 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
LLWMA-1 Wells Monitoring the Top of the Unconfined Aquifer			
299-E28-26	4/19/91	283.95	403.31
	5/24/91	283.99	403.27
	6/12/91	283.98	403.28
299-E28-27	4/19/91	277.16	403.21
	5/24/91	277.36	403.01
	6/12/91	277.20	403.17
299-E28-28	4/19/91	283.41	403.14
	5/24/91	283.42	403.13
	6/12/91	283.45	403.10
299-E32-2	4/19/91	266.95	403.11
	5/24/91	266.98	403.08
	6/12/91	266.99	403.07
299-E32-3	4/19/91	273.34	403.17
	5/24/91	273.35	403.16
	6/12/91	273.38	403.13
299-E32-4	4/19/91	282.84	403.04
	5/24/91	282.83	403.05
	6/12/91	282.83	403.05
299-E32-5	4/19/91	278.98	403.16
	5/24/91	278.98	403.16
	6/12/91	279.01	403.13
299-E33-28	4/19/91	260.94	403.29
	5/24/91	260.98	403.25
	6/12/91	260.99	403.24
299-E33-29	4/19/91	270.49	403.28
	5/24/91	270.52	403.25
	6/12/91	270.55	403.22
299-E33-30	4/19/91	260.44	403.26
	5/24/91	260.47	403.23
	6/12/91	260.47	403.23
299-E33-34	4/19/91	230.14	403.19
	5/24/91	230.17	403.16
	6/12/91	230.19	403.14
299-E33-35	4/19/91	239.85	403.16
	5/24/91	239.86	403.15
	6/12/91	239.89	403.12

4.0 200 AREAS LOW-LEVEL BURIAL GROUNDS

R. B. Mercer
Westinghouse Hanford Company

The groundwater monitoring network for the Low-Level Burial Grounds, consisting of five Low-Level Waste Management Areas (LLWMA), has not changed from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Please refer to that report for a description of the facilities and the monitoring networks.

Water level measurements for the second quarter of 1991 are presented in Table 4-1.

Table 4-1. RCRA Water Level Measurement Report Low-Level Burial Grounds - Second Quarter 1991. (sheet 3 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
299-W7-5	4/19/91	214.16	458.89
	5/24/91	214.26	458.79
	6/14/91	214.41	458.64
299-W7-6	4/19/91	219.82	458.82
	5/24/91	219.98	458.66
	6/14/91	220.11	458.53
299-W7-7	4/19/91	215.95	458.99
	5/24/91	216.09	458.85
	6/14/91	216.24	458.70
299-W7-8	4/19/91	229.71	457.64
	5/24/91	229.82	457.53
	6/14/91	229.95	457.40
299-W7-9	4/19/91	231.35	460.74
	5/24/91	231.46	460.63
	6/14/91	231.60	460.49
299-W8-1	4/19/91	240.56	460.77
	5/24/91	240.68	460.65
	6/14/91	240.84	460.49
299-W9-1	4/19/91	274.19	463.54
	5/24/91	274.33	463.40
	6/14/91	274.55	463.18

LLWMA-3 Wells Monitoring the Bottom of the Unconfined Aquifer

299-W10-14	4/19/91	235.16	464.27
	5/24/91	235.28	464.15
	6/14/91	235.45	463.98
299-W7-3	4/19/91	217.95	458.19
	5/24/91	218.10	458.04
	6/14/91	218.25	457.89

LLWMA-4 Wells Monitoring the Top of the Unconfined Aquifer

299-W15-15	6/07/91	231.44	466.52
299-W15-16	6/07/91	217.64	467.25
299-W15-18	6/07/91	218.08	467.63
299-W15-19	6/07/91	225.34	466.26
299-W15-20	6/07/91	232.28	466.08

Table 4-1. RCRA Water Level Measurement Report Low-Level Burial
Grounds - Second Quarter 1991. (sheet 2 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
LLWMA-2 Wells Monitoring the Top of the Unconfined Aquifer			
299-E27-10	6/06/91	220.74	403.73
299-E27-11	6/06/91	240.13	403.16
299-E27-8	6/06/91	234.58	403.25
299-E27-9	6/06/91	225.72	403.49
299-E34-2	4/23/91	227.31	403.49
	5/20/91	227.43	403.37
	6/18/91	227.36	403.44
299-E34-3	6/06/91	207.56	403.96
299-E34-5	4/23/91	186.43	404.36
	5/20/91	186.53	404.26
	6/18/91	186.53	404.26
299-E34-6	6/06/91	194.54	403.29
299-E34-7	6/06/91	200.80	403.47
299-E35-1	6/06/91	194.39	403.92
LLWMA-3 Wells Monitoring the Top of the Unconfined Aquifer			
299-W10-13	4/19/91	234.32	464.72
	5/24/91	234.41	464.63
	6/14/91	234.62	464.42
299-W6-2	4/19/91	232.42	460.03
	5/24/91	232.54	459.91
	6/14/91	232.71	459.74
299-W7-1	4/19/91	230.36	460.35
	5/24/91	230.47	460.24
	6/14/91	230.63	460.08
299-W7-10	4/19/91	230.33	459.33
	5/24/91	230.46	459.20
	6/14/91	230.62	459.04
299-W7-2	4/19/91	216.24	459.35
	5/24/91	216.34	459.25
	6/14/91	216.50	459.09
299-W7-4	4/19/91	210.26	461.43
	5/24/91	210.39	461.30
	6/14/91	210.53	461.16

This page intentionally left blank.

Table 4-1. RCRA Water Level Measurement Report Low-Level Burial
Grounds - Second Quarter 1991. (sheet 4 of 4)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
299-W15-23	6/07/91	233.19	466.30
299-W15-24	6/07/91	232.63	466.74
299-W18-21	6/07/91	201.81	466.81
299-W18-23	6/07/91	230.04	466.77
299-W18-24	6/07/91	216.64	467.71
299-W18-26	6/07/91	232.27	466.78
LLWMA-4 Wells Monitoring the Bottom of the Unconfined Aquifer			
299-W15-17	6/07/91	217.76	466.88
299-W18-22	6/07/91	202.44	466.05

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.

Table 5-1. RCRA Water Level Measurement Report 100-N Area - Second Quarter 1991. (sheet 1 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
Wells Monitoring the Top of the Unconfined Aquifer			
199-N-14	4/25/91	64.86	388.29
	5/30/91	63.97	389.18
	6/24/91	65.14	388.01
199-N-16	4/25/91	66.63	390.07
	5/30/91	66.35	390.35
	6/24/91	66.23	390.47
199-N-17	4/25/91	72.06	389.14
	5/30/91	71.36	389.84
	6/24/91	71.99	389.21
199-N-18	4/25/91	69.51	388.99
	5/30/91	68.62	389.88
	6/24/91	69.98	388.52
199-N-19	4/25/91	64.73	389.17
	5/30/91	63.77	390.13
	6/24/91	65.73	388.17
199-N-2	4/26/91	70.49	389.34
	5/30/91	69.59	390.24
	6/25/91	70.36	389.47
199-N-20	4/25/91	66.45	389.45
	5/30/91	65.64	390.26
	6/24/91	67.16	388.74
199-N-21	4/25/91	67.56	389.44
	5/30/91	66.62	390.38
	6/24/91	68.31	388.69
199-N-23	4/25/91	67.01	389.29
	5/30/91	65.89	390.41
	6/24/91	67.96	388.34
199-N-25	4/25/91	36.48	389.32
	5/30/91	34.83	390.97
	6/24/91	38.85	386.95
199-N-26	4/25/91	66.44	389.36
	5/30/91	65.11	390.69
	6/24/91	68.05	387.75
199-N-27	4/03/91	59.11	389.97
	4/25/91	59.10	389.98
	5/09/91	59.01	390.07
	5/30/91	59.03	390.05
	6/24/91	58.96	390.12

5.0 100-N AREA RCRA SITES

M. J. Hartman
Westinghouse Hanford Company

The 1301-N and 1324-N/NA Facilities were monitored under a groundwater quality assessment program during the past quarter (April 1 through June 30, 1991). The 1325-N site remained in a detection-level program.

Well N-57 has been substituted for well N-6 as an upgradient well to better reflect the influence of the 1324-N/NA facilities on groundwater quality (Hartman 1990).

Downgradient wells N-58, N-60, and N-61 at 1324-N/NA have too little water to sample. New wells will be installed (Hartman 1991).

Wells N-36 and N-39, formerly monitored as downgradient wells for 1325-N, have too little water to sample.

Water levels are measured monthly in most of the wells in the 100-N Area. Water levels for April, May, and June are presented in Table 5-1.

The wells in the 100-N Area networks were scheduled for sampling in June. However, because of logistical problems, only one well was sampled (N-57, sampled for the 1301-N site). Results of analyses had not been received by the end of the quarter and will be included in a future report.

Table 5-1. RCRA Water Level Measurement Report 100-N Area - Second Quarter 1991. (sheet 3 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
199-N-42	4/25/91	66.58	388.56
	5/30/91	66.18	388.96
	6/24/91	66.11	389.03
199-N-44	4/25/91	71.74	388.96
	5/30/91	71.63	389.07
	6/24/91	70.92	389.78
199-N-49	4/25/91	62.38	388.34
	5/30/91	62.07	388.65
	6/24/91	61.72	389.00
199-N-50	4/25/91	75.31	378.05
	5/30/91	74.26	379.10
	6/24/91	75.94	377.42
199-N-51	4/25/91	73.98	388.20
	5/30/91	72.32	389.86
	6/24/91	75.65	386.53
199-N-52	4/25/91	73.22	390.48
	5/30/91	73.22	390.48
	6/24/91	73.04	390.66
199-N-54	4/25/91	67.83	389.68
	5/30/91	67.54	389.97
	6/24/91	67.35	390.16
199-N-55	4/25/91	68.17	389.68
	5/30/91	67.88	389.97
	6/24/91	67.70	390.15
199-N-56	4/25/91	68.84	389.25
	5/30/91	68.37	389.72
	6/24/91	68.33	389.76
199-N-57	4/25/91	67.53	390.23
	5/30/91	67.41	390.35
	6/24/91	67.15	390.61
	6/28/91	67.20	390.56*
199-N-59	4/25/91	68.57	390.96
	5/30/91	68.40	391.13
	6/24/91	68.04	391.49
199-N-6	4/26/91	70.53	390.44
	5/30/91	71.99	388.98
	6/25/91	70.10	390.87

Table 5-1. RCRA Water Level Measurement Report 100-N Area - Second Quarter 1991. (sheet 2 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
199-N-28	4/25/91	73.84	390.40
	5/30/91	73.86	390.38
	6/24/91	73.71	390.53
199-N-29	4/25/91	74.88	390.37
	5/30/91	74.89	390.36
	6/24/91	74.69	390.56
199-N-3	4/26/91	70.08	389.37
	5/30/91	69.05	390.40
	6/25/91	70.16	389.29
199-N-31	4/25/91	72.93	389.70
	5/30/91	72.89	389.74
	6/24/91	72.58	390.05
199-N-32	4/26/91	72.30	389.78
	5/30/91	72.21	389.87
	6/24/91	71.92	390.16
199-N-33	4/25/91	70.76	389.11
	5/30/91	70.13	389.74
	6/24/91	69.70	390.17
199-N-34	4/03/91	69.69	389.94
	4/25/91	69.80	389.83
	5/09/91	69.60	390.03
	5/30/91	69.67	389.96
	6/24/91	69.48	390.15
199-N-37	4/26/91	66.80	389.32
	5/30/91	66.68	389.44
	6/24/91	66.35	389.77
199-N-39	4/26/91	65.33	388.98
	5/30/91	65.18	389.13
	6/24/91	64.71	389.60
199-N-4	4/26/91	69.12	389.61
	5/30/91	68.92	389.81
	6/25/91	68.66	390.07
199-N-40	4/26/91	67.65	388.70
	5/30/91	67.45	388.90
	6/24/91	67.02	389.33
199-N-41	4/26/91	69.38	388.21
	5/30/91	68.88	388.71
	6/24/91	68.85	388.74

Table 5-1. RCRA Water Level Measurement Report 100-N Area - Second Quarter 1991. (sheet 5 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
Wells Monitoring the Bottom of the Unconfined Aquifer			
199-N-70	4/26/91	65.22	388.99
	5/30/91	65.05	389.16
	6/24/91	64.63	389.58

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

Table 5-1. RCRA Water Level Measurement Report 100-N Area - Second Quarter 1991. (sheet 4 of 5)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
199-N-60	4/25/91	71.02	390.92
	5/30/91	70.45	391.49
	6/24/91	70.08	391.86
199-N-62	4/25/91	73.07	390.52
	5/30/91	73.08	390.51
	6/24/91	72.93	390.66
199-N-63	4/25/91	76.32	390.38
	5/30/91	76.33	390.37
	6/24/91	76.02	390.68
199-N-64	4/26/91	64.49	390.14
	5/30/91	64.38	390.25
	6/25/91	64.00	390.63
199-N-65	4/26/91	66.59	389.85
	5/30/91	66.45	389.99
	6/25/91	66.14	390.30
199-N-66	4/26/91	75.70	389.55
	5/30/91	75.48	389.77
	6/25/91	75.20	390.05
199-N-67	4/26/91	69.57	388.89
	5/30/91	68.77	389.69
	6/25/91	69.29	389.17
199-N-8S	4/11/91	15.26	389.31
	4/25/91	15.67	388.90
	5/09/91	16.10	388.47
	6/25/91	18.04	386.53
699-81-58	4/26/91	44.64	394.91
	5/30/91	44.78	394.77
	6/24/91	44.85	394.70

Wells Monitoring the Bottom of the Unconfined Aquifer

199-N-69	4/26/91	69.94	388.90
	5/30/91	69.17	389.67
	6/25/91	69.77	389.07

Table 6-1. RCRA Water Level Measurement Report 216-A-29 Ditch - Second Quarter 1991. (sheet 1 of 2)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
Wells in the Detection Monitoring System			
299-E25-26	4/17/91	264.60	403.92*
	4/18/91	264.54	403.98
	5/24/91	264.62	403.90
	6/13/91	264.58	403.94
299-E25-28	4/10/91	258.62	403.82*
	4/17/91	258.25	404.19*
	4/18/91	258.37	404.07
	5/24/91	258.38	404.06
	6/13/91	258.44	404.00
299-E25-32P	4/11/91	266.15	403.89*
	4/18/91	266.17	403.87
	5/24/91	266.04	404.00
	6/13/91	266.12	403.92
299-E25-34	4/10/91	258.92	403.95*
	4/18/91	258.90	403.97
	5/24/91	258.90	403.97
	6/13/91	258.98	403.89
299-E25-35	4/17/91	270.78	403.61*
	4/18/91	270.78	403.61
	5/24/91	270.54	403.85
	6/13/91	270.83	403.56
699-43-43	4/18/91	164.34	415.03
	5/23/91	164.21	415.16
	6/13/91	164.20	415.17
699-43-45	4/18/91	192.93	404.75
	5/23/91	193.03	404.65
	6/13/91	192.91	404.77
Supplemental Wells for Assessment Monitoring			
299-E25-10	6/10/91	252.24	403.60
299-E25-11	6/10/91	277.79	403.49
299-E25-18	6/10/91	275.50	403.55
299-E25-19	6/10/91	273.78	403.42
299-E25-20	6/10/91	272.91	403.39

6.0 216-A-29 DITCH

G. L. Kasza
Westinghouse Hanford Company

The 216-A-29 Ditch currently is in groundwater quality assessment monitoring. The 216-A-29 groundwater quality assessment monitoring activities and expanded monitoring well network are described in a previous quarterly report (DOE-RL 1990).

The groundwater monitoring network for the 216-A-29 Ditch is in compliance with the applicable regulations since the release of the Ground Water Monitoring Plan for the 216-A-29 Ditch (Kasza 1991). In accordance with the plan, two additional RCRA-compliant wells (699-43-43 and 699-43-45) have been added to the network to act as the groundwater monitoring network upgradient wells.

Water levels are measured monthly in the wells comprising the 216-A-29 Ditch monitoring network and quarterly for the surrounding wells that provide supplemental data for the groundwater quality assessment investigation. Water level measurements obtained during this quarter are presented in Table 6-1.

No wells in the detection monitoring network were sampled during the report period. One of the supplemental wells for the assessment program was sampled in late June. No analytical information was returned in time for inclusion in this report.

This page intentionally left blank.

91129 02062

Table 6-1. RCRA Water Level Measurement Report 216-A-29 Ditch - Second Quarter 1991. (sheet 2 of 2)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
299-E25-31	6/10/91	268.85	403.68
	6/25/91	268.78	403.75*
299-E25-36	6/20/91	304.15	403.24
299-E25-6	6/10/91	257.32	400.99
299-E25-9	6/10/91	253.31	401.55
299-E26-2	6/10/91	231.36	403.94

NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
 2. Depth-to-water values are transcribed from field records.
 3. Elevations marked with an '*' were measured at the time of sampling.

Table 7-1. RCRA Water Level Measurement Report 216-A-10 Crib -
Second Quarter 1991.

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
299-E17-1	6/20/91	316.27	402.90
299-E17-19	6/20/91	316.69	402.64
299-E17-20	6/20/91	316.40	402.83
299-E24-16	6/20/91	315.19	403.08
299-E24-17	6/20/91	316.53	402.16
299-E24-18	6/20/91	316.08	403.20
299-E24-2	6/20/91	314.54	402.93
299-E25-36	6/20/91	304.15	403.24

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

7.0 216-A-10 Crib

**D. K. Tyler
Westinghouse Hanford Company**

The groundwater monitoring network for the 216-A-10 Crib has not changed from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Please reference that quarterly for a description of the monitoring network.

Water level measurements for the second quarter of 1991 are reported in Table 7-1.

Table 8-1. RCRA Water Level Measurement Report 216-A-36B Crib -
Second Quarter 1991.

Well	Date	Depth of water (ft)	Water level elevation above msl (ft)
299-E17-14	6/20/91	319.06	403.12
299-E17-15	6/20/91	319.35	402.43
299-E17-16	6/20/91	317.58	403.00
299-E17-17	6/20/91	316.83	403.09
299-E17-18	6/20/91	317.41	403.24
299-E17-5	6/20/91	316.02	402.67
299-E17-6	6/20/91	314.66	402.98

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

8.0 216-A-36B Crib

D. K. Tyler
Westinghouse Hanford Company

The groundwater monitoring network for the 216-A-36B Crib has not changed from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Please reference that quarterly for a description of the monitoring network.

Water level measurements are the only activities that have occurred during the second quarter of 1991. These data are reported in Table 8-1.

Table 9-1. RCRA Water Level Measurement Report 216-B-3 Pond System
- Second Quarter 1991. (sheet 1 of 2)

Well	Date	Depth water (ft)	Water level elevation above msl (ft)
Wells Monitoring the Unconfined Aquifer at the Water Table			
299-E18-1	6/05/91	316.74	403.50
299-E32-4	4/19/91	282.84	403.04
	5/24/91	282.83	403.05
	6/12/91	282.83	403.05
699-42-40A	4/18/91	123.04	422.49
	5/23/91	122.59	422.94
	6/13/91	122.84	422.69
699-43-42J	4/18/91	162.48	419.20
	5/23/91	162.14	419.54
	6/13/91	162.37	419.31
699-43-43	4/18/91	164.34	415.03
	5/23/91	164.21	415.16
	6/13/91	164.20	415.17
699-43-45	4/18/91	192.93	404.75
	5/23/91	193.03	404.65
	6/13/91	192.91	404.77
699-44-42	4/18/91	158.33	420.89
	5/23/91	158.24	420.98
	6/13/91	158.29	420.93
699-44-43B	4/18/91	164.65	415.47
	5/23/91	164.62	415.50
	6/13/91	164.48	415.64
Wells Monitoring the Confined or Semi-Confined Aquifer			
699-40-39	4/15/91	128.27	413.57*
	4/18/91	128.31	413.53
	5/23/91	128.42	413.42
	6/13/91	128.39	413.45
699-41-40	4/15/91	129.68	416.26*
	4/18/91	129.78	416.16
	5/23/91	129.80	416.14
	6/13/91	129.56	416.38
699-43-41E	4/18/91	129.76	421.10*
	4/18/91	129.71	421.15
	5/23/91	129.51	421.35
	6/13/91	129.38	421.48
	6/28/91	129.22	421.64*

9.0 216-B-3 POND SYSTEM

C. D. Delaney
Westinghouse Hanford Company

There have been no changes to the 216-B-3 Pond System groundwater monitoring network from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Only one well from the 216-B-3 Pond System groundwater monitoring network was sampled between April 1 and June 30, 1991. Well 699-43-41E was sampled on June 28, 1991 and will be discussed in the next quarterly report.

Water level data collected for the second quarter of 1991 are presented in Table 9-1.

This page intentionally left blank.

0
1
2
3
4
5
6
7
8
9
10
11
12
13
14
15
16
17
18
19
20
21
22
23
24
25
26
27
28
29
30
31
32
33
34
35
36
37
38
39
40
41
42
43
44
45
46
47
48
49
50
51
52
53
54
55
56
57
58
59
60
61
62
63
64
65
66
67
68
69
70
71
72
73
74
75
76
77
78
79
80
81
82
83
84
85
86
87
88
89
90
91
92
93
94
95
96
97
98
99
100

Table 9-1. RCRA Water Level Measurement Report 216-B-3 Pond System
- Second Quarter 1991. (sheet 2 of 2)

Well	Date	Depth water (ft)	Water level elevation above msl (ft)
699-43-41F	4/18/91	129.75	421.26*
	4/18/91	129.72	421.29
	5/23/91	129.33	421.68
	6/13/91	129.47	421.54

Well Monitoring the Unconfined Aquifer Below the Water Table

699-42-42B	4/18/91	166.03	417.20
	5/23/91	165.82	417.41
	6/13/91	165.83	417.40

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

Table 10-1. RCRA Water Level Measurement Report 2101-M Pond - Second Quarter 1991.

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
299-E18-1	6/05/91	316.74	403.50
299-E18-3	6/05/91	318.58	403.46

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.

10.0 2101-M POND

M. A. Chamness
Pacific Northwest Laboratory

The groundwater monitoring network for the 2101-M Pond has not changed from that described in the quarterly report for the period July 1 through September 30, 1990 (DOE-RL 1990). Please reference that quarterly for a description of the monitoring network.

Water level data collected for the second quarter of 1991 are presented in Table 10-1.

Table 11-1. RCRA Water Level Measurement Report Grout Treatment Facility
- Second Quarter 1991. (sheet 1 of 2)

Well	Date	Depth of water (ft)	Water level elevation above msl (ft)
299-E25-18	6/10/91	275.50	403.55
299-E25-20	6/10/91	272.91	403.39
299-E25-24	6/25/91	275.66	403.89
299-E25-25	6/25/91	264.96	404.46
	6/25/91	264.93	404.49*
299-E25-26	4/17/91	264.60	403.92*
	4/18/91	264.54	403.98
	5/24/91	264.62	403.90
	6/13/91	264.58	403.94
299-E25-27	6/25/91	272.11	403.97
299-E25-28	4/10/91	258.62	403.82*
	4/17/91	258.25	404.19*
	4/18/91	258.37	404.07
	5/24/91	258.38	404.06
	6/13/91	252.44	410.00 -X
299-E25-29P	6/25/91	271.58	401.28 -X
	6/25/91	269.76	403.10*
299-E25-29Q	6/25/91	268.95	403.67
299-E25-30Q	6/25/91	274.44	403.47
299-E25-31	6/10/91	268.85	403.68
	6/25/91	268.78	403.75*
299-E25-32P	4/11/91	266.15	403.89*
	4/18/91	266.17	403.87
	5/24/91	266.04	404.00
	6/13/91	266.12	403.92
299-E25-32Q	6/25/91	265.98	404.06
299-E25-33	6/25/91	246.42	403.61
	6/27/91	256.29	393.74*-X
299-E25-37	6/25/91	269.67	403.62
	6/26/91	269.68	403.61*

11.0 GROUT TREATMENT FACILITY

D. K. Tyler
Westinghouse Hanford Company

The groundwater monitoring network for the Grout Treatment Facility has not changed from that described in the quarterly report for the period October 1, 1990 through December 31, 1990 (DOE-RL 1991a). Please reference that quarterly for a description of the monitoring network. During the second quarter of 1991, water levels were measured and water chemistry samples were collected.

Water chemistry samples were collected in the last days of the second quarter. Analytical results were not available for verification at the time this report was prepared; these will be included in the next quarterly report.

Water level measurements obtained for the second quarter of 1991 are listed in Table 11-1. Some water level data for wells 299-E25-28, 299-E25-29P, and 299-E25-33 are suspected of being in error. A review is being performed to determine the source of error and to make corrections, if appropriate.

This page intentionally left blank.

91122 02076

Table 11-1. RCRA Water Level Measurement Report Grout Treatment Facility
- Second Quarter 1991. (sheet 2 of 2)

Well	Date	Depth of water (ft)	Water level elevation above msl (ft)
299-E25-38	6/25/91	269.70	403.82
	6/26/91	269.65	403.87*
299-E25-39	6/10/91	266.58	404.65
	6/26/91	266.86	404.37*

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.
4. Data suspected of being in error are marked '-X' and are under review.

Table 12-1. RCRA Water Level Measurement Report Single-Shell Tanks - Second Quarter 1991. (sheet 1 of 3)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
241-A/AX Tank Farm Wells			
299-E24-13	4/25/91	287.66	403.47
	5/22/91	287.63	403.50
	6/17/91	287.82	403.31
299-E24-19	4/24/91	290.27	403.38
	5/21/91	290.28	403.37
	6/17/91	290.25	403.40
299-E25-1	4/25/91	287.04	403.53
	5/22/91	287.04	403.53
	6/17/91	287.25	403.32
299-E25-13	4/25/91	278.90	403.53
	5/22/91	278.89	403.54
	6/04/91	278.73	403.70*
	6/17/91	279.10	403.33
299-E25-15	4/25/91	286.21	403.52
	5/22/91	286.21	403.52
	6/17/91	286.40	403.33
299-E25-2	4/24/91	272.04	403.41
	5/21/91	271.84	403.61
	6/19/91	272.11	403.34
299-E25-40	4/24/91	262.16	403.55
	5/20/91	262.16	403.55
	6/17/91	262.22	403.49
299-E25-41	4/24/91	267.64	403.62
	5/20/91	267.66	403.60
	6/17/91	267.74	403.52
241-B/BX/BY Tank Farm Wells			
299-E33-18	4/24/91	240.37	403.25
	5/21/91	240.25	403.37
	6/19/91	240.30	403.32
299-E33-21	4/24/91	264.88	403.25
	5/20/91	264.86	403.27
	6/17/91	264.86	403.27

12.0 SINGLE-SHELL TANKS

J. A. Caggiano
Westinghouse Hanford Company

The groundwater monitoring network for the Single-Shell Tanks (SST) is being expanded with the addition of 10 new RCRA Standard wells at Waste Management Areas B-BX-BY, S-SX, TX-TY, and U. Construction of these 10 new RCRA groundwater monitoring wells is scheduled to begin in August 1991. Water levels measured in 30 wells for the quarter are provided in Table 12-1.

The last of the eleven calendar year 1990 RCRA standard groundwater monitoring wells were completed at the SSTs in June 1991. No other field activities took place this quarter. Wells 299-E33-38 and 299-E33-39, CERCLA remedial investigation wells for the 200-BP-1 Operable Unit, have been completed in the unconfined aquifer on the northern margin of Waste Management Area (WMA) B-BX-BY. Well 299-E33-36, a downgradient RCRA standard well for the 216-B-63 Trench, also will be used for groundwater monitoring. Water level and some constituent data will be obtained from these wells as part of the SST network for WMA B-BX-BY. There are now 26 RCRA standard groundwater monitoring wells at the SSTs (including wells 299-E33-36, 299-E33-38, and 299-E33-39).

Table 12-1. RCRA Water Level Measurement Report Single-Shell Tanks - Second Quarter 1991. (sheet 3 of 3)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
241-T Tank Farm Wells			
299-W10-10	4/24/91	210.97	464.12
	5/21/91	211.02	464.07
	6/17/91	211.38	463.71
299-W10-11	4/24/91	210.87	464.39
	5/21/91	210.88	464.38
	6/17/91	211.26	464.00
299-W10-12	4/24/91	210.58	464.17
	5/21/91	210.70	464.05
	6/17/91	210.98	463.77
299-W10-15	4/24/91	211.53	464.11
	5/21/91	211.55	464.09
	6/17/91	211.92	463.72
299-W10-16	4/24/91	208.34	464.42
	5/21/91	208.36	464.40
	6/17/91	208.65	464.11
299-W10-3	4/24/91	207.01	464.45
	5/21/91	208.17	463.29 -X
	6/18/91	207.32	464.14
299-W10-8	4/24/91	216.24	463.81
	5/21/91	216.29	463.76
	6/19/91	216.34	463.71
299-W10-9	4/24/91	210.52	464.15
	5/21/91	213.95	460.72
	6/17/91	210.83	463.84
299-W11-23	4/24/91	222.03	463.39
	5/21/91	222.05	463.37
	6/19/91	222.06	463.36
299-W11-24	4/24/91	223.30	463.87
	5/21/91	223.35	463.82
	6/19/91	223.34	463.83

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.
4. Data suspected of being in error are marked '-X' and are under review.

Table 12-1. RCRA Water Level Measurement Report Single-Shell Tanks - Second Quarter 1991. (sheet 2 of 3)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
299-E33-24	4/24/91	234.35	403.35
	5/21/91	234.38	403.32
	6/19/91	234.43	403.27
299-E33-31	4/25/91	244.02	403.26
	5/20/91	244.04	403.24
	6/17/91	244.03	403.25
299-E33-32	4/24/91	256.72	403.11
	5/20/91	256.68	403.15
	6/17/91	256.67	403.16
299-E33-33	4/24/91	236.87	403.30
	5/20/91	236.94	403.23
	6/17/91	236.80	403.37
299-E33-8	4/25/91	247.45	403.28
	5/20/91	247.45	403.28
	6/17/91	247.48	403.25
241-C Tank Farm Wells			
299-E27-12	4/24/91	257.57	403.38
	5/20/91	257.58	403.37
	6/17/91	257.61	403.34
299-E27-13	4/24/91	265.68	403.31
	5/20/91	265.73	403.26
	6/17/91	265.74	403.25
299-E27-14	4/24/91	254.78	403.56
	5/20/91	254.89	403.45
	6/17/91	254.82	403.52
299-E27-15	4/24/91	249.59	403.08
	5/20/91	249.65	403.02
	6/17/91	249.67	403.00
299-E27-7	4/24/91	231.13	403.54
	5/20/91	231.12	403.55
	6/17/91	231.15	403.52

Table 13-1. RCRA Water Level Measurement Report NRDWL - Second Quarter 1991. (sheet 1 of 2)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
NRDWL Wells Monitoring the Top of the Unconfined Aquifer at the Water Table			
699-25-34A	4/22/91	127.24	402.77
	5/23/91	127.27	402.74
	6/12/91	127.38	402.63
699-25-34B	4/17/91	126.32	402.81*
	4/22/91	126.28	402.85
	5/23/91	126.35	402.78
	6/12/91	126.46	402.67
699-26-33	4/22/91	132.68	402.81
	5/23/91	132.69	402.80
	6/12/91	132.82	402.67
699-26-34	4/22/91	125.25	402.84
	5/23/91	125.29	402.80
	6/12/91	125.40	402.69
699-26-35A	4/22/91	129.48	402.89
	5/23/91	129.54	402.83
	6/12/91	129.66	402.71
NRDWL Wells Monitoring the Upper Ringold			
699-25-33A	4/22/91	125.67	402.88
	5/23/91	125.76	402.79
	6/12/91	125.86	402.69
699-26-35C	4/22/91	129.23	402.90
	5/23/91	129.29	402.84
	6/12/91	129.44	402.69
Solid Waste Landfill Monitoring Wells			
699-23-34	4/22/91	130.01	402.85
	5/23/91	130.07	402.79
	6/12/91	130.19	402.67
699-24-34A	4/22/91	131.04	402.85
	5/23/91	131.10	402.79
	6/12/91	131.22	402.67
699-24-34B	4/22/91	130.62	402.88
	5/23/91	130.70	402.80
	6/12/91	130.79	402.71

13.0 NONRADIOACTIVE DANGEROUS WASTE LANDFILL

F. N. Hodges
Westinghouse Hanford Company

The groundwater monitoring network for the Nonradioactive Dangerous Waste Landfill (NRDWL) has not changed from that described in the quarterly report for the period July 1 through September 30, 1991 (DOE-RL 1990). Please reference that quarterly for a description of the monitoring network. No monitoring activities other than water level measurements have taken place during the second quarter of 1991.

The water level data collected for the second quarter of 1991 are presented in Table 13-1.

This page intentionally left blank.

Table 13-1. RCRA Water Level Measurement Report NRDWL - Second Quarter 1991. (sheet 2 of 2)

Well	Date	Depth to water (ft)	Water level elevation above msl (ft)
699-24-34C	4/22/91	129.76	402.82
	5/23/91	129.81	402.77
	6/12/91	129.92	402.66
699-24-35	4/22/91	135.94	402.87
	5/23/91	136.00	402.81
	6/12/91	136.10	402.71
699-25-34C	4/22/91	132.61	402.85
	5/23/91	132.67	402.79
	6/12/91	132.77	402.69
Other Wells Associated with NRDWL			
699-20-20	4/22/91	104.28	401.30
	5/23/91	104.34	401.24
	6/12/91	104.48	401.10
699-20-39	4/22/91	136.74	403.24
	5/23/91	136.87	403.11
	6/12/91	136.96	403.02
699-24-33	4/22/91	121.43	402.78
	5/23/91	121.50	402.71
	6/12/91	121.63	402.58
	6/20/91	121.47	402.74*
699-28-40	4/22/91	156.17	403.27
	5/23/91	156.30	403.14
	6/12/91	156.40	403.04
699-31-31	4/22/91	126.55	402.77
	5/23/91	126.62	402.70
	6/12/91	126.72	402.60
699-34-39A	4/22/91	133.75	403.32
	5/23/91	133.85	403.22
	6/12/91	133.93	403.14

- NOTES: 1. Water level elevations are calculated by subtracting the measured depth to water from the surveyed elevation for the well.
2. Depth-to-water values are transcribed from field records.
3. Elevations marked with an '*' were measured at the time of sampling.

14.0 REFERENCES

- Comprehensive Environmental Response, Compensation and Liability Act of 1980*, Public Law 96-510, 94 Stat. 2767, 42 USC 9601 et seq.
- DOE-RL, 1990, *Quarterly Report of RCRA Groundwater Monitoring Data for Period July 1, 1990 through September 30, 1990*, DOE/RL-90-46, U.S. Department of Energy-Richland Operations Office, Richland, Washington.
- DOE-RL, 1991a, *Quarterly Report of RCRA Groundwater Monitoring Data for Period October 1, 1990 through December 31, 1990*, DOE/RL-91-04, U.S. Department of Energy-Richland Operations Office, Richland, Washington.
- DOE-RL, 1991b, *Quarterly Report of RCRA Groundwater Monitoring Data for Period January 1, 1991 through March 31, 1991*, DOE/RL-91-26, U.S. Department of Energy-Richland Operations Office, Richland, Washington.
- Ecology, 1991, *Dangerous Waste Regulations*, Washington Administrative Code WAC 173-303, Washington State Department of Ecology, Olympia, Washington.
- EPA, 1989, *Interim Status Standards for Owners and Operators of Hazardous Waste Treatment, Storage, and Disposal Facilities*, Title 40 Code of Federal Regulations, Part 265, as amended, U.S. Environmental Protection Agency, Washington, D.C.
- Hartman, M. J., 1990, *Results of Ground Water Quality Assessment Monitoring at the 1301-N Liquid Waste Disposal Facility and 1324-N/NA Facilities*, WHC-SD-EN-EV-003, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- Hartman, M. J., 1991, *Groundwater Monitoring Plan for the 1301-N, 1324-N/NA, and 1325-N Facilities*, WHC-SD-EN-AP-038, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- Kaza, G. L., 1991, *Ground Water Monitoring Plan for the 216-A-29 Ditch*, WHC-SD-EN-AP-045, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- Resource Conservation and Recovery Act of 1976*, Public Law 94-580, 90 Stat. 2795, 42 USC 6901 et seq.
- Teel, S. S., B. N. Bjornstad, and D. R. Newcomer, 1989, *Interim Status Groundwater Monitoring Plan for the Grout Treatment Facility*, WHC-SD-EN-AP-006, Rev. 0, Westinghouse Hanford Company, Richland, Washington.
- WHC, 1991, *Environmental Investigation and Site Characterization Manual*, WHC-CM-7-7, Westinghouse Hanford Company, Richland, Washington.

DISTRIBUTION (continued)

Number of copies

M. A. Mihalic	L4-88
F. A. Ruck	H4-57
R. E. Peterson	H4-56
R. D. Pierce	N3-13
S. M. Price	H4-57
W. H. Price	S0-03
J. S. Schmid (15)	H4-56
J. A. Serkowski	H4-56
L. C. Swanson	H4-56
R. R. Thompson	L4-88
D. K. Tyler	H4-56
B. A. Williams	H4-56
C. D. Wittreich	H4-55
R. F. Wood	R4-01
J. F. Woods	G4-07
Central Files	L8-04
EDMC (3)	H4-22
Publications Services (3)	H4-17

DISTRIBUTION

Number of copies

ONSITE

9

U.S. Department of Energy-
Richland Operations Office

R. J. Nevarez	A5-21
M. W. Tiernan	A5-55
M. J. Furman (4)	A5-21
R. A. Gilbert	A5-21
Public Reading Room (2)	A1-65

5

Pacific Northwest Laboratory

J. V. Borghese	K6-96
M. A. Chamness	K6-96
M. A. Neely	K6-96
R. M. Smith	K6-96
Technical Files	K1-11

1

Westinghouse Savannah River Company

R. C. Tuckfield

59

Westinghouse Hanford Company

M. R. Adams	H4-55
D. J. Brown	B4-63
J. A. Caggiano	H4-56
J. W. Cammann	H4-14
C. D. Delaney	H4-56
J. J. Dorian	B2-16
D. B. Erb	R1-51
K. R. Fecht	H4-56
B. H. Ford	H4-56
E. A. Gordon	H4-17
M. J. Hartman	H4-56
F. N. Hodges	H4-56
D. G. Horton	H4-56
R. L. Jackson	H4-56
V. G. Johnson	H4-56
D. H. Jones	H4-16
G. L. Kasza	H4-56
A. J. Knepp	H4-56
R. J. Landon	B2-19
A. G. Law	H4-56
M. Marratt	H4-56
M. M. McCarthy	N3-13
R. B. Mercer	H4-56